

Denial of Service Vulnerability in EagleSDV

Date: 2022-08-01

Version: 1.0

Summary

EagleSDV crashes on session establishment using TLS1.0 or TLS1.1.

Affected Products

Brand	Product Line / Platform	Product	Version
Hirschmann	Eagle	EagleSDV	05.4.01

Solution

Updates are available, which address the vulnerabilities. Customers are advised to update their product.

Brand	Product Line / Platform	Product	Version
Hirschmann	Eagle	EagleSDV	05.4.02

For Help or Feedback

To view all Belden Security Bulletins or to report suspected security vulnerabilities, go to <https://www.belden.com/security>.

For technical support and other requests, please visit <https://hirschmann-support.belden.com> and <https://garrettcom-support.belden.com>.

Related Links

Disclaimer

THE SECURITY BULLETIN, AND INFORMATION CONTAINED HEREIN, ARE PROVIDED ON AN "AS IS" BASIS AND DO NOT IMPLY ANY KIND OF GUARANTEE OR WARRANTY, INCLUDING THE WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE. YOUR USE OF THE BULLETIN, AND INFORMATION CONTAINED HEREIN, OR MATERIALS LINKED FROM THE BULLETIN, IS AT YOUR OWN RISK. INFORMATION IN THIS BULLETIN AND ANY RELATED COMMUNICATIONS IS BASED ON OUR KNOWLEDGE AT THE TIME OF PUBLICATION AND IS SUBJECT TO CHANGE WITHOUT NOTICE. BELDEN RESERVES THE RIGHT TO CHANGE OR UPDATE BULLETINS AT ANY TIME.

Revisions

V1.0 (2022-08-01)

Bulletin created.